



**Swedish Certification Body for IT Security**

## Maintenance Report - HP GIF HCDPP

**Issue: 2.0, 2020-Apr-27**

*Authorisation: Jerry Johansson, Lead Certifier , CSEC*

Swedish Certification Body for IT Security  
Maintenance Report - HP GIF HCDPP

Table of Contents

<b>1</b>	<b>Introduction</b>	<b>3</b>
<b>2</b>	<b>Description of Changes</b>	<b>5</b>
2.1	Affected evaluation evidence	5
2.2	Conclusion	5
<b>3</b>	<b>References</b>	<b>6</b>

# 1 Introduction

On 10 October 2019, a Maintenance Impact Analysis Report [MIAR11] was submitted to CSEC, as part of a request from HP Inc. to extend the validity of the Common Criteria certificate previously awarded to:

HP LaserJet Enterprise MFP M631/M632/M633,

HP Color LaserJet Enterprise MFP M681/M682,

HP LaserJet Managed MFP E72525/E72530/E72535/E82540/E82550/E82560/  
E62555/E62565/E62575,

HP Color LaserJet Managed MFP E77822/E77825/E77830/E87640/E87650/  
E87660/E67550/E67560.

The process to achieve this under mutual recognition is described in “Assurance Continuity: CCRA Requirements” [AC]. In accordance with [AC], the [MIAR11] describes all changes done to the TOE and/or its IT environment, all resulting changes done to the evaluation evidence, and the security impact of the changes.

The process of extending the validity of a certificate to an updated product is referred to below as “certificate maintenance”.

It should be noted that the assessment of the certification body skipped a few formal steps (related to project planning) and went directly from review of the maintenance application to finalising the maintenance report.

This does not follow CSEC's written procedures, but for such a simple project the need for planning is small. This approach was chosen in agreement between the certifiers and the operations manager.

This is an administrative update of the first version of this Maintenance Report which does not affect the original decision dated 2019-10-29.

Swedish Certification Body for IT Security  
Maintenance Report - HP GIF HCDPP

Previously Certified TOE	
Certification ID	CSEC2017011
Certified TOE version	<p>HP LaserJet Enterprise MFP M631/M632/M633</p> <p>MFP firmware version 2405143_000032</p> <p>JDI firmware version JSI24050403</p> <p>HP Color LaserJet Enterprise M681/M682,</p> <p>MFP firmware version 2405143_000033</p> <p>JDI firmware version JSI24050403</p> <p>HP LaserJet Managed MFP E72525/E72530/E72535</p> <p>MFP firmware version 2405143_000035</p> <p>JDI firmware version JSI24050403</p> <p>HP LaserJet Managed MFP E82540/E82550/E82560</p> <p>MFP firmware version 2405143_000030</p> <p>JDI firmware version JSI24050403</p> <p>HP LaserJet Managed MFP E62555/E62565/E62575</p> <p>MFP firmware version 2405143_000032</p> <p>JDI firmware version JSI24050403</p> <p>HP Color LaserJet Managed MFP E77822/E77825/E77830</p> <p>MFP firmware version 2405143_000031</p> <p>JDI firmware version JSI24050403</p> <p>HP Color LaserJet Managed MFP E87640/E87650/ E87660</p> <p>MFP firmware version 2405143_000034</p> <p>JDI firmware version JSI24050403</p> <p>HP Color LaserJet Managed MFP E67550/E67560</p> <p>MFP firmware version 2405143_000033</p> <p>JDI firmware version JSI24050403</p>
Assurance package	<p>for CCRA and EA_MLA:</p> <p>Protection Profile for Hardcopy Devices v1.0 with Errata #1, including ASE_INT.1, ASE_CCL.1, ASE_SPD.1, ASE_OBJ.1, ASE_ECD.1, ASE_REQ.1, ASE_TSS.1, ADV_FSP.1, AGD_OPE.1, AGD_PRE.1, ALC_CMC.1, ALC_CMS.1, ATE_IND.1, and AVA_VAN.1</p> <p>for SOGIS:</p> <p>EAL 1 + ASE_SPD.1</p>
Sponsor	HP Inc.
Developer	HP Inc.
ITSEF	atsec information security AB
Common Criteria version	3.1 release 5
CEM version	3.1 release 5
Certification date	2018-10-22

## 2 Description of Changes

The changed made to the TOE has been subject to the following changes:

1. The previously evaluated product includes a Seagate ST500LT015 self-encrypting drive (SED) that is FIPS 140-2 validated (CMVP #1826), but the validation reached its scheduled sunset date in September 2019. The disk therefore has now been replaced with a Common Criteria certified (VID10857) and FIPS 140-2 validated (CMVP #2695) self-encrypting disk drive (SED), Seagate ST500LM033.

In the evaluation, the self-encrypting drive is covered by an SFR, FDP\_DSK\_EXT.1, which requires that the SED has been CC certified/validated against the Full Disk Encryption Protection Profile. Since the only impact on the evaluation evidence and the evaluation activities is that the name of the SED has been changed in the documentation, the change should be categorized as minor, following the guidelines in [AC].

### 2.1 Affected evaluation evidence

The affected evaluation evidence is:

1. The Security Target
2. Key Management Description
3. The Administrative Guidance
4. Additional test documentation

The changes in (1-3) were made to change the information specific to the SED and its validations. The additional test documentation (4) shows that the new SED initialization works and results in the intended operational state.

The TOE hardware and firmware is unchanged.

### 2.2 Conclusion

The changes done to the TOE has not in any way changed the hardware or firmware of the TOE, only the Security Target, the Key Management Description, and the Administrative Guidance were updated with the name and validation information for the new SED, and test evidence showing that the new SED works as intended were added.

The changes apply to functionality located in the operational environment, and are therefore categorized as minor, so that certificate maintenance according [AC] applies.

The conclusion is that the assurance gained during the original evaluation and certification for

HP LaserJet Enterprise MFP M631/M632/M633,

HP Color LaserJet Enterprise M681/M682,

HP LaserJet Managed MFP E72525/E72530/E72535/E82540/E82550/E82560/  
E62555/E62565/E62575, and

HP Color LaserJet Managed MFP E77822/E77825/E77830/E87640/E87650/  
E87660/E67550/E67560

remains after changing the self-encryption drive delivered with the product.

### 3 References

MIAR11	Maintenance Impact Analysis Report, HP LaserJet Enterprise MFP M631/M632/M633, HP Color LaserJet Enterprise M681/M682, HP LaserJet Managed MFP E72525/E72530/E72535/E82540/E82550/E82560/ E62555/E62565/E62575, HP Color LaserJet Managed MFP E77822/E77825/E77830/E87640/E87650/ E87660/E67550/E67560, atsec information security AB, 2019-10-10, document version 1.1
MIAR10	Maintenance Impact Analysis Report, HP LaserJet Enterprise MFP M631/M632/M633, HP Color LaserJet Enterprise M681/M682, HP LaserJet Managed MFP E72525/E72530/E72535/E82540/E82550/E82560/ E62555/E62565/E62575, HP Color LaserJet Managed MFP E77822/E77825/E77830/E87640/E87650/ E87660/E67550/E67560, atsec information security AB, 2019-08-19, document version 1.0
TEST	GIF_CD_New_HDD_Configuration Pages, FMV ID 19FMV4660-7
STnew	HP LaserJet Enterprise MFP M631/M632/M633, HP Color LaserJet Enterprise M681/M682, HP LaserJet Managed MFP E72525/E72530/E72535/E82540/ E82550/E82560/E62555/E62565/E62575, HP Color LaserJet Managed MFP E77822/E77825/E77830/ E87640/E87650/E87660/E67550/E67560 Security Target, HP Inc., 2019-08-02, document version 2.1, FMV ID 19FMV4660-3
STcert	HP LaserJet Enterprise MFP M631/M632/M633, HP Color LaserJet Enterprise M681/M682, HP LaserJet Managed MFP E72525/E72530/E72535/E82540/ E82550/E82560/E62555/E62565/E62575, HP Color LaserJet Managed MFP E77822/E77825/E77830/ E87640/E87650/E87660/E67550/E67560 Security Target, HP Inc., 2018-09-05, document version 2.0, FMV ID 17FMV7100-45
CRcert	Certification Report, HP GIF HCDPP, FMV/CSEC, 2018-11-27, document version 2.0, FMV ID 17FMV7100-41:1
AC	Assurance Continuity: CCRA Requirements, 2012-06, document version 2.1
HCDPP	Protection Profile for Hardcopy Devices, IPA/NIAP/MFP TC, 2015-09-10, document version 1.0

Swedish Certification Body for IT Security  
Maintenance Report - HP GIF HCDPP

ERRATA      Protection Profile for Hardcopy Devices - v1.0 Errata#1  
June 2017, IPA/NIAP/HCD TC, 2017-06-27